



LCD cutout and holes slightly undersize